



**BHAVAN NIRMAN**

ARCHITECTS, ENGINEERS & VALUERS

■ ■ ■ Daulat Press Main Road, Bhavan Nirman, Near Railway Station, Opp. Fire Brigade, Veraval-362265.  
■ ■ ■ Email - bhavannirmandoc1@gmail.com

REF.

DATE:-

27/06/2019

REF:- BNAE/VRL/BUC/TWSEIMC/3133

## **BUILDING USE PERMISSION/UTILITY** **CERTIFICATE**

### **TO WHOM SO EVER IT MAY CONCERN:-**

This is to certify that the school Bldg. of "NANJI KALIDAS D.A.V. PUBLIC SCHOOL" The school bldg. is located village Sidheegram (Morasa), Ta. Sutrapada, Dist. - Gir - Somnath. Which is handling by "D.A.V. COLLEGE TRUST & MANAGEMENT SOCIETY, CHITRAGUPT ROAD - NEW DELHI, IN COLLABORATION WITH GUJARAT SIDHEE CEMENT LTD. - SIDHEEGRAM MORASA". The School bldg. has been visited by me on dated 26/06/2019 & I found the following points about the structure of the school Bldg. as follows.

Owner: - "GUJARAT SIDHEE CEMENT LTD. - SIDHEEGRAM (MORASA)".

- Foundation : - 2'6" wide & up to depth of hard strata, filled with UCR.  
Plinth : - From UCR masonry with C.C. Coping.  
Super structure : - 0.23 Mts. Thick W.S. Bella fitted with cement - sand Slurry.  
RCC Works : - Lintels, Chhajjas & Roof from RCC works of nece. Size & Thickness.  
Finishing : - Cement plaster inside & outside.  
Flooring : - From mosaic tiles.  
Other features : - Doors & windows from non - teak wood, iron grills, color Coating inside & outside.  
Light & ventilation: - The adequate light & ventilation provided, Hygienic Condition for school living and educating.  
Height : - 10'00 height of the floor i.e. from floor level to slab level 10'00 height.





**BHAVAN NIRMAN**  
ARCHITECTS, ENGINEERS & VALUERS

- ■ ■ Daulat Press Main Road, Bhavan Nirman, Near Railway Station, Opp. Fire Brigade, Veraval-362265.
- ■ ■ Email - bhavannirmandoc1@gmail.com

REF.

DATE:-

27/06/2019

### Report about the stability of the school Bldg.: -

I found no cracks, brakes & other const. Defects anywhere in the school bldg. it is found safe & sound from all the ways. It is stand in good & stable position. There are no chances of Bldg. fallen down or collapse at any simple natural circumstances.

### Conclusion: -

The school Bldg. Found safe & sound. No cracks, brakes & other defects found In the Bldg. can remain stable for years in simple natural circumstances.  
The school bldg. is structurally stable at my opinion.

Date: - 27/06/2019  
Place: - Veraval

Krishnkant A. Pandat  
(Cha. Architect, Engineer & Govt. Regd. Valuer)

**KRISHNKANT A. PANDAT**  
B. Arch. A. I. I. A.,  
Architect & Govt. Regd. Valuer  
Regd. No. CA/88/11826  
VERAVAL - 362 265.



**BHAVAN NIRMAN**

ARCHITECTS, ENGINEERS & VALUERS

Govt. Approved Valuer (Under Wealth tax 34AB Approved),  
LCM - 2443, CAT-I - Immoveable Properties, LCM - 2443, CAT-II - Agri. Lands,  
LCM - 2445, CAT-VII - Plant & Machinery.  
Registered Engineer . Structural Designer of Nagar Palika

- ■ ■ Daulat Press Main Road, Bhavan Nirman, Near Railway Station, Opp. Fire Brigade, Veraval-362265.
- ■ ■ Email - bhavannirmandoc1@gmail.com

REF.

DATE:-

27/06/2019

